

FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL

AHLERS AEROSPACE, INC.
3621 RAIDER DRIVE
HURST, TX 76053

PMA No. PQ0948SW
Supplement No. 1
Revision No.
Project No. PM1977RC-R

Part Name	Part Number	Approved Replacement for Part Number	Approval Basis and Approved Design Data	Make Eligibility	Model Eligibility
RPM Warning Sensor	801-40011	206-075-545-1	Test and Computations per 14CFR § 21.303, Drawing: 801-40011, Rev: A, Dated: 4/28/00, or later FAA approved revisions.	Bell Helicopter Textron Canada Limited	206A, 206B, 206L
RPM Warning Sensor	801-40015	206-075-545-5	Test and Computations per 14CFR § 21.303, Drawing: 801-40015, Rev: A, Dated: 4/28/00, or later FAA approved revisions.	Bell Helicopter Textron Canada Limited	206A, 206B, 206L

-----End of Listing-----

NOTE: Provide minor design changes in a manner determined by the ACO. Handle major design changes to drawings and specifications in the same manner as that for an original FAA-PMA. If TC holder's ICA applies to these replacement parts, provide a statement noting such. If not, provide supplementary ICA per 14 CFR § 21.50.



MAY 06 2008

Vaughn N. Schmitt
Manager, Manufacturing Inspection District Office,
SW-MIDO-42

Date

This Supplement is an attachment to your FAA-PMA approval letter dated: ~~MAY 05 2008~~